



- KEY
- ▶

Vehicle access from New Link Road or University Road West

▶

Athletics Track general access

▶

Design to respond to key views into site

5%

Min. 5% of car park area to have soft landscaping treatment

Ground levels along site boundary to co- ordinate with existing levels outside of the boundary

Minimum extent of car park

Maximum extent of car park

⊕ 145.60

Key levels indicated

Min 37 trees to be planted.

For indicative information on ground levels refer 0504-A-HA-16-301

NOTE:

For clarity existing trees not shown on this drawing.
-
- Project 16abc: Replacement Development on Site of Munrow Sports Centre
Parameters Plan - scale 1:500
- Replacement Development on Site of Munrow Sports Centre comprises:

 - New Standard Athletics Track with Triple Jump Facility, with flood lights
 - New Sports Pavilion
 - Car Park V
 - ground works and landscaping
-
- Detail 1- New Link Road Arrangement adjacent to Car Park R
- | Rev | Date | Description | By | Chk | App |
|-----|------------|-------------------------|----|-----|-----|
| - | 02.03.2012 | PLANNING ISSUE | TF | LP | LP |
| A | 09.03.2012 | RE- ISSUED FOR PLANNING | TF | LP | LP |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
- | GENERAL NOTES | ALL INFORMATION SUBJECT TO STATUTORY APPROVALS BEING OBTAINED |
|--|--|
| DO NOT SCALE DRAWINGS. USE FIGURED DIMENSIONS ONLY. | ALL INFORMATION SUBJECT TO STATUTORY APPROVALS BEING OBTAINED |
| ALL DIMENSIONS TO BE CHECKED ON SITE DISCREPANCIES TO BE REPORTED IMMEDIATELY TO THE ARCHITECT | INFORMATION NOT TO BE USED OTHER THAN AS DEFINED BY THE DRAWING STATUS |
| FOR STRUCTURAL DIMENSIONS AND SETTING OUT SEE STRUCTURAL ENGINEERS DRAWINGS | |
- Edgbaston Central Campus Development

Hybrid Planning Application

Project 16abc: Replacement Development on Site of Munrow Sports Centre

Parameters Plan

9 HENEAGE STREET, SPITALFIELDS, LONDON, E1 5LJ

Drawing No. 0504 - A HA- 16 - 300 - A

Scale 1:500 @ A1

File Name N/A

Date 01/02/2012

NOTE DO NOT SCALE DRAWINGS. ALL DIMENSIONS TO BE CHECKED ON SITE. ERRORS TO BE REPORTED IMMEDIATELY TO THE ARCHITECT
-
- P:\0504-A-HA-16-300-A\0504-A-HA-16-300-A.dwg 14/03/2012